

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

BRUCEMORE
Linn County
Cedar Rapids
Iowa

HABS No. IA-196

Leslie Schwartz Photography, 1990

- IA-196-1 EXTERIOR, SOUTH ELEVATION, VIEW FORM THE SOUTH LOOKING NORTH
- IA-196-2 EXTERIOR, SOUTHWEST ELEVATION, VIEW LOOKING NORTH
- IA-196-3 EXTERIOR, CHIMNEY DETAIL, SOUTHWEST CORNER, VIEW LOOKING
NORTHEAST
- IA-196-4 EXTERIOR, NORTHWEST ELEVATION, VIEW LOOKING SOUTHEAST
- IA-196-5 EXTERIOR, NORTH ELEVATION, VIEW LOOKING SOUTH
- IA-196-6 EXTERIOR, EAST ELEVATION, VIEW LOOKING WEST
- IA-196-7 INTERIOR, GREAT HALL LOOKING TOWARD STAIR AND ENTRANCE HALL,
FIRST FLOOR, SOUTH WALL VIEW FROM THE NORTH LOOKING SOUTH
- IA-196-8 INTERIOR, FROM FIRST FLOOR STAIR LANDING DOWN TO THE GREAT
HALL, BETWEEN FIRST AND SECOND FLOORS, NORTH WALL, VIEW FROM
SOUTH LOOKING NORTH
- IA-196-9 INTERIOR, GREAT HALL LOOKING TOWARD THE LIBRARY, FIRST FLOOR,
SORTH AND WEST WALLS, VIEW FROM THE SOUTHWEST LOOKING
NORTHWEST
- IA-196-10 INTERIOR, LIBRARY WITH THE FIREPLACE, FIRST FLOOR, NORTH AND
WEST WALLS, VIEW FORM THE SOUTHEAST LOOKING NORTHWEST
- IA-196-11 INTERIOR, SITTING ROOM, FIRST FLOOR, SOUTHWEST WALL, VIEW FORM
THE NORHTEAST LOOKING SOUTHWEST
- IA-196-12 INTERIOR, DINING ROOM INCLUDING THE FIREPLACE, FIRST FLOOR, EAST
WALL, VIEW FORM THE SOUTHWEST LOOKING NORTHEAST
- IA-196-13 INTERIOR, CENTRAL STAIR LOOKING INTO THE BOUDIOR, SECOND FLOOR,
EAST WALL, VIEW FROM THE NORTHEAST LOOKING SOUTHWEST
- IA-196-14 INTERIOR, SWAN ROOM BEDROOM, THIRD FLOOR, NORTH AND WEST
WALL, VIEW FORM SOUTHEAST LOOKING NORTHWEST